B.R No: 386/2015-16 **Date: 27-11-15**

INSPECTION REPORT FOR THE WORK OF:

CONSTRUCTION OF CULVERTS IN DIFFERENT LOCATIONS AT MALLASANDRA AREA IN WARD NO-13 IN SHETTYHALLI SUB-DIVISION

By

Sri K.Manjunath

INSPECTION REPORT

Name of Work	:	CONSTRUCTION OF CULVERTS IN DIFFERENT LOCATIONS AT MALLASANDRA AREA IN WARD NO-13 IN SHETTYHALLI SUB-DIVISION
Work Order	:	EE/DD/WO/216/2013-14 DATE: 27-01-2014
Agency	:	B.T.RAVIKUMAR
B.R No & Date	:	386/2015-16 DATE: 27-11-15
Bill Amount	:	14,92,330/-
Job Code	:	013-14-000004
P. Code	:	P-1771
Date of Inspection	:	18-11-2016

The above said work "Construction of culverts in Different locations at Mallasandra Area in ward no-13 Shettyhalli Sub Div." was shown to me by the Concerned ward Engineer.

The above said work is inspected by me along with the Concerned ward Engineer.

The work done is Satisfactory.

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of work :- Constution of Culverts in different loctions at Mallasandra area in ward No 13. Shettyhalli Sub-division

BR No :- 386/2015-16 dated :- 27-11-15





MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

NAME OF CONSRUTON OF CULVERTS IN DIFFRENT WORK & LOCTIONS AT MALLESANDRA AREA in WARD NO: 13 SHETTYHALLI SUB-DIVISON.

B.R. NO: 386/2015-16 dated: 27-11-15

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

NAME OF WORK : CONSRUCTON OF CULVERTS in DIFFRENT LOCTONS AT MALLASANDRA AREA INWARD NO: 13 SHETTYHALLI SUB-DIVISION

B.R NO: 386/2015-16 date: 27-11-15

ದಿ ಂ/ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (P
PUBLIC WORKS DEPARTM